

Basic Strip Dimensional Formula: A = (No. of positions-1) x 0.050" 1st to last contacts. B = A + 0.075" - overall without ears. C = A + 0.200" - center to center of mounting holes. D = A + 0.375" - overall with ears.